Revised 08/05

CORRES. CONTROL INCOMING LTR NO.

00428_RF05

DUE DATE

RECEIVED

2005 AUS 22 A 6: 46

Department of Energy

CORRESPONDENCE CONTROL

ROCKY FLATS PROJECT OFFICE 12101 AIRPORT WAY, UNIT A BROOMFIELD, COLORADO 80021-2583

AUG 1.6 2005

DIST. LTR ENC BERARDINI, J.H BOGNAR, E.S. BROOKS, CARPENTER, M DEGENHART, K. R. FERRERA, D. W. GIACOMINI, J. J. LINDSAY, D. C LONG, J. W NESTA, S. SHELTON, D. C TUOR, N. R. WARD, D. WIEMELT, K ZAHM, C. Hebu Rothmern

Mr. Carl Spreng
RFCA Coordinator
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, CO 80222-1530

Dear Mr. Spreng:

Please find enclosed completed Rocky Flats Cleanup Agreement (RFCA) Type 1 building disposition Closeout Report provided for your information for Buildings 764 & 765 PIDAS and alarm system building, DWF-078-05 dated August 9, 2005. This request is submitted in accordance with the RFCA for your review and comment.

Questions can be directed to Gary Morgan, RFPO, at (303) 966-6003.

Sincerely,

John J. Rampe, Director

RFPO Closure Project Management

Enclosure

cc w/o Encl:

S. Nesta, K-H RISS Env

J. Heber, K-H RISS D&D

K. Wiemelt, K-H RISS D&D

Reviewed for Addressee Corres. Control RFP

COR. CONTROL

8/22/05

Ref. Ltr. # 0512F00743

DOE ORDER #

cc w/Encl:

D. Kruchek, CDPHE

M. Aguilar, USEPA

D. Abelson, RFCLOG

K. Korkia, RFCAB

Administrative Record



05-DOE-00523

ADMIN RECORD

1/6



August 9, 2005

05-RF-00763

Gary Morgan, Director Project Support DOE, RFPO

TRANSMITTAL OF CLOSE OUT REPORT FOR BUILDING 764 AND 765-- DWF-078-05

Attached is the Closeout Report for the Type 1 Building 764 and Building 765. Please note that a copy of the report has been submitted to the CERCLA AR by the Kaiser-Hill RISS project.

Please contact Steve Nesta x6386 with questions or concerns.

7.8. Mbb for D. U. Terre

Dennis W. Ferrera

Vice President and Project Manager

Remediation, Industrial D&D, and Site Services

Attachment:

As Stated

SMN:jlh

Orig. and 1 cc - Gary Morgan

CC:

John Rampe

Kaiser-Hill Company, L.L.C.
Rocky Flats Environmental Technology Site, 12101 Airport Way, Unit B, T130F, Golden, (*() 80403-8200 ● (303) 966-6386

Type 1 Facility Closeout Report

				
Section A. Facility Data	l			
Facility No.	Building 764 and Building 765			
Facility Descriptor:	Building 764 was the PIDAS building			
	Building 765 was the secondary alarm system building			
Project:	RISS			
Date of Demolition:	July 20, 2005			
Additional Information:				
(Must include information on environmental releases and conditions of site at turnover to Environmental Restoration)				
Section B. Final Characterization Data				
Reconnaissance Level Cha	racterization Re	port	Reconnaissance Level Characterization Report for Buildings	
(Concurrence received)			750, 764, 765, and Trailers 750A, B, C, D, F, & G	
			Concurrence, Steven H. Gunderson to Joseph A. Legare,	
•			dated July 24, 2003.	
In-process Characterization	ım.		NA	
Pre-Demolition Survey Re		المصنف	NA NA	
			NA NA	
Post-Demolition Survey R	eport (as necessar)		IVA .	
Section C. Waste Data (complete categories as appropriate)				
Sanitary Disposal			IF-F	
Disposal Site:	В	FI Foo	thills 93 Landfill, Golden, CO	
Waste Volume (m ³):		733.97		
Waste Weight (tons):		9.28		
Additional Information:			neous building debris including concrete, metal and asphalt	
			,	
Hazardous Disposal				
Disposal Site:		Kettleman Hills Facility, Kettleman City, CA or Bethlehem Apparatus		
			ertown, PA	
Waste Volume (pounds):		00 lbs.		
Additional Information:		Minor amounts of electronic circuit boards, thermostats, exit signs,		
			, fluorescent light bulbs and any other RCRA hazardous	
			ents were removed and taken to the RFCA temporary unit for	
			tion with like waste streams for disposal. Additionally, there	
•			roximately 500 lbs of nickel-cadmium UPS batteries that will for disposal.	
		SCIIL I	oi disposai.	
Asbestos Waste Disposal			·	
Disposal Site:				
Waste Volume (m ³):			·	
Additional Information:				
Low-Level Waste Disposal				
Disposal Site:		•		
Waste Volume (m ³):				
Additional Information:				
Low-Level Mixed Waste D	<u>isposal</u>		·	
Disposal Site:				
Waste Volume (m ³):				
Additional Information:				
Property Disposition			Market State of the Control of the C	
Receiver Locations (major	items only):			
Additional Information:				
Availional Impi Mativili			7002 o i eu	
Section D. Approvals		/		
Kaiser-Hill Project Manager	J.W.C	711	Ann / Som & SOS	
renou-rim r roject manager	Name/Signatur		Date	
	14amoroignatui	<u> </u>	to be because and a manufacture of the particular of the particula	

Additional Information

Building 764 was the PIDAS Building. The building housed computerized alarm and surveillance equipment. The building also housed the Uninterrupted Power Supply Battery system for Buildings 764 and 765. Building 764 was 1763 square feet concrete block structure with a steel roof and built-up insulation.

Building 764 had the following utilities: electric, plant water, plant sanitary, and fire protection provided by an overhead sprinkler system.

Building 765 was a secondary security alarm system building and was used for backup to the security and alarm systems in Building 121. Building 765 was a 960 square foot concrete block structure with a steel roof and built-up insulation.

Building 765 had the following utilities: electric, plant water, plant sanitary and fire protection provided by an overhead sprinkler system.

All of the facilities structures were removed to three feet below the final grade.

Utilities were all removed/disconnected as shown on the attached map.



